

Estrategia de Fabricación Avanzada 2020



REFERENCIAS DE OFERTA TEIC BI 4.0


TRIMEK, S.A.






Multisensor Massive Measurement

DIMENSIONAL METROLOGY
IN MOTION




Introducción: Metrology 4.0





Casos de referencia: EPC

- Comprehensive quality inspection **traceability** process across the **supply chain**



Casos de referencia: EPC

- Comprehensive quality inspection traceability process across the supply chain



Avances tecnológicos: Cyber Physical

Production Systems


m3 gage

m3 server

m3 tablet

Cyber

r



Physical



Cotas erróneas

instalar

Menú: Selección pieza > Colocación pieza > Medición > Resultado > Cotas erróneas

Cerrar sesión

Cotas erróneas y críticas

Código	Descripción	Medida	Valor	Unidad	Valor	Unidad	Valor	Unidad
000735	1117.08	1138.236	0.25	-0.25	0.236			
000737	1100.34	1100.574	0.25	-0.25	0.234			
000740	882.2	880.487	0.25	-0.25	0.007			
000742	844.56	844.789	0.25	-0.25	0.229			
000744	880.06	880.289	0.25	-0.25	0.229			
000749	733.28	733.51	0.25	-0.25	0.231			
000753	640.14	640.37	0.25	-0.25	0.23			
000755	602.5	600.756	0.25	-0.25	0.256			
000758	861.36	861.613	0.25	-0.25	0.253			
000760	110.72	110.881	0.25	-0.25	0.261			
000762	391.22	391.19	0.25	-0.25	0.27			

Imagotek

camassist

Apuntar la pieza con el contrator
haciendo tope en el fondo que los
cilindros del contrator toquen la pieza.

Anterior 3/4 Siguiente

camassist

 gage

 server

 tablet

